

**Maine Yankee Atomic Power Company
Historic Site Assessment**

for

**Spent Fuel Waste
Inventories
(Onsite, Offsite, Environment)**

and

**Fuel Cladding Failure Accident
Source Terms
(Release Quantities, Locations,
Pathways, and Destinations)**

**Final Site Survey
Integrated Database**

H. G. Brack, Ed.

The Davistown Museum
Department of Environmental History

Table of Contents

Abstract

Operational History Summary

Oak Ridge National Laboratory Integrated Database for Spent Fuel Wastes

 Biologically Significant Radionuclides

 Integrated Database Summary

First Fuel Cladding Failure Accident

Source Term Definition

 Release Quantity

 Release Location

 Pathways

 Destinations

Early Surveillance Reports

Hot Particle Contamination

The Vaughn Bowen Survey

1984 Reactor Water Tank Leak

Steam Generator Safety Issues

The Power Uprate Scam

Later Fuel Cladding Failure Accidents

GTS Duratek Site Characterization

MYAPC Historic Site Assessment

 Onsite Locations

 Reactor Vessel

 Spent Fuel Pool

 Independent Spent Fuel Storage Installation (ISFSI)

 Reactor Water Tank and Water Systems

 Other Buildings

 Offsite Locations

 South Carolina

 Nevada

 Other

 Environment

 Onsite – Soil

 Offsite – Soil

 Montsweag Bay

Rapid Decommissioning Significance

Unresolved Spent Fuel Waste Storage Issues

 Yucca Mountain

 ISFSI Life Expectancy

 Spent Fuel Pool Debris

Conclusions